

PUB. 116

# LIST OF LIGHTS

RADIO AIDS AND FOG SIGNALS

2002

**IMPORTANT**

THIS PUBLICATION  
SHOULD BE CORRECTED  
EACH WEEK FROM THE  
NOTICE TO MARINERS

## BALTIC SEA

WITH KATTEGAT, BELTS AND SOUND  
AND GULF OF BOTHNIA



Prepared and published by the  
NATIONAL IMAGERY AND MAPPING AGENCY  
Bethesda, MD


© COPYRIGHT 2002 BY THE UNITED STATES GOVERNMENT.  
NO COPYRIGHT CLAIMED UNDER TITLE 17 U.S.C.

For sale by the Superintendent of Documents, U.S. Government Printing Office  
Internet: bookstore.gpo.gov Phone: toll free (866) 512-1800; DC area (202) 512-1800  
Fax: (202) 512-2250 Mail Stop: SSOP, Washington, DC 20402-0001



NSN 7642014007540  
NIMA REF. NO. LLPUB116

# LIST OF LIGHTS LIMITS NATIONAL IMAGERY AND MAPPING AGENCY



**116**

**LIGHTS**

**BALTIC SEA**

**2002**

## WARNING ON USE OF FLOATING AIDS TO NAVIGATION TO FIX A NAVIGATIONAL POSITION

The aids to navigation depicted on charts comprise a system consisting of fixed and floating aids with varying degrees of reliability. Therefore, prudent mariners will not rely solely on any single aid to navigation, particularly a floating aid.

The buoy symbol is used to indicate the approximate position of the buoy body and the sinker which secures the buoy to the seabed. The approximate position is used because of practical limitations in positioning and maintaining buoys and their sinkers in precise geographical locations. These limitations include, but are not limited to, inherent imprecisions in position fixing methods, prevailing atmospheric and sea conditions, the slope of and the material making up the seabed, the fact that buoys are moored to sinkers by varying lengths of chain, and the fact that buoy and/or sinker positions are not under continuous surveillance but are normally checked only during periodic maintenance visits which often occur more than a year apart. The position of the buoy body can be expected to shift inside and outside the charting symbol due to the forces of nature. The mariner is also cautioned that buoys are liable to be carried away, shifted, capsized, sunk, etc. Lighted buoys may be extinguished or sound signals may not function as the result of ice or other natural causes, collisions, or other accidents.

For the foregoing reasons, a prudent mariner must not rely completely upon the position or operation of floating aids to navigation, but will also utilize bearings from fixed objects and aids to navigation on shore. Further, a vessel attempting to pass close aboard always risks collision with a yawing buoy or with the obstruction the buoy marks.